

8 7 NOTES: 1. USE ASSEMBLY INSTRUCTIONS 5511198 FOR ATTACHING DAK TO PXI 2. MATING ITA MODULE P/N 561401. 3. SUPPLED WITH MOUNTING HARDWARE. 4. SEE SHEET 3 FOR WIRE LIST.	<u>6 5</u> CARD.	4	3		2 1	ι
	L. C.		æ			
8 7	6 5	BALLOON LEGEND PART NUMBER QTY 4	.XX ±.03 .XX ±.01 ±.20 mm .XXX ±.010 .XXX ±.005 ±.100 mm .XXX ±.010 .XXX ±.005 ±.100 mm REMOVE ALL BURRS AND BREAK SHARP EDGES. EDGES. EDGES.	DRAWN BY 03/12/2007 WKM 03/12/2007 GAC 03/12/2007 OPERATIONS 03/12/2007 RAMDFACTURING 03/12/2007 ASSEMBLY 03/12/2007 MATERIAL USED -	TITLE DAK ASSY, SCOUT, SGL, PXI-4110	3

8		7		6	 5	4	3	2	 1
NOTES:									
1. USE ASSEMBLY I 2. MATING ITA MO 3. SUPPLIED WITH	DULE P/N 561	401.	Aching dak to	PXI CARD.					

4. SEE SHEET 3 FOR WIRE LIST.

D

F

Α

8

7

6

5

561126WL									
MAC 561301 J1	6 Position Combicon	MAC 561301 J1	2 Position Combicon						
1	D	10	В						
2	E	11	С						
3	F								
4	G								
5	н								
6	I								

	MAC P. This document may of	ANEL PROPRIETAR' ontain confidential	DRAWN BY WKM	03/12/2007	MAC PANEL COMPANY - HIGH POINT, NC						
	information that is the property of MAC Panel Company that may not be disclosed to, or duplicated for others except as authorized by MAC Panel Company.			ENGINEERING GAC	03/12/2007	TITLE					
				OPERATIONS C.BOGGS	03/12/2007						
BALLOON LEGEND	TOLERANCES (UNLESS C SHEET METAL MACHINED		,	MANUFACTURING R.SPIVEY	03/12/2007	DAK	DAK ASSY, SCOUT, SGL, PXI-4110				
PART NUMBER	ANGLES ± 1' ANGLES ± 1'	Projection	ASSEMBLY								
QTY	.XXX ±.010 .XXX ±	.01 ± .20 mm .005 ± .100 mm .0005 ± .0100 mm	$\square \oplus$	MATERIAL USED	I	C		DWG NO	!6-cu		
	REMOVE ALL BURRS AND	EMOVE ALL BURRS AND BREAK SHARP EDGES.		-		SCALE	1/1 SP	N: 561143	SHEET 3 OF 3		
4			3			2			1	-	

In