







Receiver



ITA



301016-01



832D65

COMMENTS / NOTES

The principle is wherever an 832D65 is located in the ITA a 301016-01 can not be located in the Receiver hole aligning with the same hole so ensuring only the correct ITA will engage with the Receiver.

○○○○○○○
MAC-PANEL


WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
09/05/2012

DESCRIPTION

Operation Description for
561344



DRAWING NO.

561344-CU

REVISION

0

SHEET

1 OF 1