

COMMENTS / NOTES

Example of an APEX PCB Assembly using Headers to enable simple Contact replacement.

MAC-PANEL


WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
22/12/2017

DESCRIPTION

PCB_APEX_260



Third Angle
Projection


DRAWING NO.

PCB_APEX_260-CU

REVISION

B

SHEET
1 OF 4



COMMENTS / NOTES

Exploded view of parts with Headers.

MAC-PANEL


WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
22/12/2017

DESCRIPTION

PCB_APEX_260




DRAWING NO.

PCB_APEX_260-CU

REVISION

B

SHEET
2 OF 4



COMMENTS / NOTES

Both Assembled and Exploded view of parts without Headers.
But difficult to remove contacts.

MAC-PANEL

WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
22/12/2017

Third Angle
Projection


SHEET
3 OF 4

DESCRIPTION

PCB_APEX_260

DRAWING NO.
PCB_APEX_260-CU

REVISION
B



COMMENTS / NOTES

Hole Layout for PCB Holes
View is Component side if used with 562331.




WWW.MACPANEL.COM

DRAWN BY
davecooper

DATE
22/12/2017

DESCRIPTION



SHEET
4 OF 4

DRAWING NO.

APEX_260_PCB_Ex-CU

REVISION

B